



Product Safety Recall



Do you own this product?

In & Outboard Marine - Lithium Battery Systems (LBS) lithium iron phosphate batteries

Lithium iron phosphate batteries, labelled LBS and typically used in marine applications.

The affected lithium iron phosphate batteries are the:

- 12V 110Ah
- 12V 150Ah
- 24V 110Ah
- 24V 150Ah
- 36V 110Ah

Affected model numbers:

12110-SP, 12110-SP-VM-MRN, 12150-SP, 12150C-SP-VM-MRN, 12150C-DCS10-ST, 12150-SP-VM-MRN, 24110-SP, 24110-SP-VM-MRN, 24150-SP, 24150-SP-MRN, 24150-SP-VM-MRN, 36110-SP, 36110-SP-VM-MRN, 36110-SP-ST.

Dates sold by In & Outboard Marine:
8 July 2020 – 17 May 2023



Why the product is recalled: There are defects in the battery management system, and insufficient sealing of the battery casing that can cause corrosion. These defects can cause the batteries to leak, overheat or catch fire.

Hazard: There is a risk of smoke and gas inhalation poisoning, serious injury, death, and damage to property if the batteries leak, overheat or catch fire.



Consumers should stop using the battery immediately, remove the battery, and store the battery in a cool area.

Consumers should return the battery to the place of purchase to arrange for the battery to be refunded.



For more information, consumers can contact In & Outboard Marine by email with the subject 'Recall' at recall@iomarine.com

PRA 2023/19834

See [productsafety.gov.au](https://www.productsafety.gov.au) for
Australian product recall information